FIELD INSPECTION REPORT District: E. Champaro Date of Inspection:  $04-12\cdot2020$ Length (Km): 2.27 kg Chakia Division: Name of the Road: Chakia To kesaria PWD Road Pakadi dirit MAINTENANCE (New) Scheme/Programme: Road ID No .: 31708202069 . Package No.: Status of the Project : Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up Gradation/ Maintenance SI. No. Parameters to be checked Remarks 1, **Pavement** a) Road Junction condition b) **Condition of Surfacing** C) **Riding Quality** d) Road Camber Whether free from defects such as visible cracks, exposed aggregates in e) case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) g) Compaction of flank/slope & raincuts if any 2, **Cross Drainage** S, a) Condition of head walls in Hume pipe culverts including its painting b) Condition of Abutment & Wing walls, Slab in RCC Culverts C) Condition of railings/slab/approach for Bridges 3, Road Furniture Whether sign board/informatory/cautionary Board/Km & 200m a) Stones/Pavement road markings are provided and maintained 151

Overall Rating : Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Remarks: - Some points in this food required floors but land are not poor plant sail Pilling.

NAME:

4,

a)

DESIGNATION:

**Compliance History** 

Status of ATR's & any others

04.12.2020 J.E (Signature)