FIELD INSPECTION REPORT Date of Inspection: 04-12-2020 District: E. Champaro Division: Chakia 2.063 KM Length (Km): Name of the Road: Cawandri fo khafolwa (New) Scheme/Programme: MAINTENANCE 31708202082 Road ID No.: Package No.: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up Gradation/ Maintenance Work is a case of : Remarks SI. No. Parameters to be checked 1, **Pavement** احا a) **Road Junction condition** 121 b) Condition of Surfacing 151 c) **Riding Quality** d) **Road Camber** Whether free from defects such as visible cracks, exposed aggregates in e) case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) 151 g) Compaction of flank/slope & raincuts if any 2, **Cross Drainage** a) Condition of head walls in Hume pipe culverts including its painting b) Condition of Abutment & Wing walls, Slab in RCC Culverts c) Condition of railings/slab/approach for Bridges 3. **Road Furniture** Whether sign board/informatory/cautionary Board/Km & 200m a) Stones/Pavement road markings are provided and maintained

Overall Rating : Satisfactory (S)
Satisfactory but requires improvement (SRI)
Unsatisfactory (U)

NAME :

4, a)

DESIGNATION:

Compliance History

Status of ATR's & any others

04.12.2020 04.12.2020 (Signature)