

# FIELD INSPECTION REPORT

| Date of Inspection: 04/12/2020                                |                                                                                                                      | District: East Chumbor |
|---------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|------------------------|
| Division: Arveya                                              |                                                                                                                      | Length (km): 6.24      |
| Name of the Road: Jogi To Bauriya Dih                         |                                                                                                                      |                        |
| Scheme/Programme: MAINTENANCE                                 |                                                                                                                      |                        |
| Package No.: MR-N/19-20 Arveya                                |                                                                                                                      | Read Id No.: 317282628 |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                                                                                                                      |                        |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                                                                                                                      |                        |
| Sl. No.                                                       | Parameters to be checked                                                                                             | Remarks                |
| I.                                                            | Pavement                                                                                                             |                        |
| a)                                                            | Road Junction condition                                                                                              | S/C                    |
| b)                                                            | Condition of Surfacing                                                                                               | S/U                    |
| c)                                                            | Riding Quality                                                                                                       | S/U                    |
| d)                                                            | Road Camber                                                                                                          | S/U                    |
| e)                                                            | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | N/A                    |
| f)                                                            | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No                 |
| g)                                                            | Compaction of flank/slope & raincuts if any                                                                          | Yes/No                 |
| II. Culverts                                                  |                                                                                                                      |                        |
| a)                                                            | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SR/U                 |
| b)                                                            | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SR/U                 |
| c)                                                            | Condition of railings/slab/approach for Bridges                                                                      | N/A                    |
| III. Roadside Infrastructure                                  |                                                                                                                      |                        |
| a)                                                            | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No                 |
|                                                               |                                                                                                                      |                        |
|                                                               |                                                                                                                      |                        |
| IV. Summary (S)                                               |                                                                                                                      | S                      |
| V. Summary but requires Improvement (SRI)                     |                                                                                                                      |                        |
| VI. Summary (U)                                               |                                                                                                                      |                        |

8/12/2020  
(Signature)