FIELD INSPECTION REPORT

-		TILLD HOT LOTTE	NAME OF TAXABLE PARTY OF TAXABLE PARTY.		
Date of Inspection: 04-12-2020 District: E. Champ				h	
			4		
Name of the Road: Kotwa - Kalyanpur Road me Dewpur Bairiya Pak					
Scheme/Programme: MAINTENANCE (A/ew) Package No.: Road ID No.: 31708202100					
Package I	02/00				
Status of the Project :		Ongoing/Completed/Under Maintenance			
Work is a case of :		New Connectivity/Up Gradation/ Maintenance			
SI. No.	Parameters to be checked Remarks			Remarks	
1,	Pavement				
. a)	Road Junction condition			's'	
b)	Condition of Surfacing			151	
c)	Riding Quality			's'	
d)	Road Camber			<u>'s'</u>	
e)	Whether free from de	-			
f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/s	's '			
2,	Cross Drainage				
a)	Condition of used waits in nume pipe curverts including its painting			' s '	
_ b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			51	
c)	Condition of railings/slab/approach for Bridges			15'	
3,	Road Furniture				
a)	Whether sign board/informatory/cautionary Board/Km & 200m			's'	
4,	Stones/Pavement road markings are provided and maintained Compliance History				
a)	Status of ATR's & any	others			
			L		

Overall Rating :

Satisfactory (S)	15'
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

04.12.2020

(Signature)