

FIELD INSPECTION REPORT

Date of Inspection: 04/12/2020	District: East. Chharpada
Division: Chalgia.	Length (Km): 1.897 km
Name of the Road: Nehsi Katta LGO Road to Motnaye Bandh	
Scheme/Programme:	MAINTENANCE (New Maintenance policy 2015)
Package No.:	Road ID No.:

Status of the Project:	Ongoing/Completed/Under Maintenance ☒
Work is a case of:	New Connectivity/Up Gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road section condition	'S'
b)	Condition of Surfacing	'S'
c)	Riding Quality	'S'
d)	Road Camber	'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3.	Road Furniture	
a)	Whether sign board/Informatory/cautionary Board/Km & 200m Stone/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	(S)
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

NAME :
DESIGNATION :

Zela
04/12/2020
VE

04/12/2020
A.E

(Signature)

Zela
04/12/2020

04/12/2020
A.E