

FIELD INSPECTION REPORT

Date of Inspection : 06/12/2020		District : E. Champaran.	
Division : Chakia.		Length (Km): 1.10 km.	
Name of the Road : Narhar Patsi PWD road to Bharthuli'a.			
Scheme/Programme :		MAINTENANCE (New)	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement		
a)	Road Junction condition	—	
b)	Condition of Surfacing	—	
c)	Riding Quality	—	
d)	Road Camber	—	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—	
f)	Contraction Joints provided or not (CC Pavement)	—	
g)	Compaction of flank/slope & raincuts if any	—	
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	—	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—	
c)	Condition of railings/slab/approach for Bridges	—	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	—	
4,	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :	Satisfactory (S)	—
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

Remarks:- work yet to be started.

NAME :

DESIGNATION :

Abhi
06/12/2020
JE

(Signature)