

FIELD INSPECTION REPORT

Date of Inspection: 05/12/2020		District: East Champaran
Division: Mithila		Length (km): 1.120
Name of the Road: P.O. Road to Amla		
Scheme/Programme: MAINTENANCE		
Package No.: 17-20	17-20	Road Id No.: 51/0202155
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
S. No.	Parameters to be checked	Remarks
I.	Pavement	
a)	Road Junction condition	S/S
b)	Condition of Surfacing	S/S
c)	Riding Quality	S/S
d)	Road Camber	S/S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/R/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S/R/U
c)	Condition of railings/slab/approach for Bridges	N/A S/S/R/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
a)	Status of ATR's & any others	NO

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 4/15
5/12/2020

DESIGNATION: A.E. RWD
Avery -