

FIELD INSPECTION REPORT

Date of Inspection : 24/12/2020	District: East Champaran
Division : Ayeyar	Length (km): 4.210
Name of the Road: P.W.D Road To Jado pur	
Scheme/Programme: MAINTENANCE	
Package No.: MR N/1272 Ayeyar	Road Id No.: 317.8202165
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Particulars	Remarks
I.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

24/12/2020
(Signature)

NAME: Harendra Lal

DESIGNATION: AO RWD

Arady