

FIELD INSPECTION REPORT


Date of Inspection : 05/12/2020		District : E. Champaran.
Division : Chakia.		Length (Km): 2.932 km.
Name of the Road : R.E.O Road to Bishunpura.		
Scheme/Programme :		MAINTENANCE
Package No.:		Road ID No.:
Status of the Project :		☒ Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	-S-
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

Remarks:- Work under progress.

NAME :

DESIGNATION :


 05/12/2020
 DE

(Signature)