	FIELD INSPECTION REP	One of bandon respect of	-
ale of Inspection: DY	2 20 20 District	: East-Chan	-paron
usion: che	Ja'a. Length	(Km): 1.013 h	M
of the Road : PU	rami Mensi me Mor	The Allice He	_ () ()
eine/Programme :	MAINTENANCE (Now Main	te have Palicya.	27 8)
lage No.:	Road II		
ius of the Project:	of the Project: Ongoing/Completed/Under Maintenance		
h is a case of:	New Connectivity/Up Gradation/	Maintenance /	
No. Parameters to be ch			Romarks
Pavement			
Road Junction cond	lition	144	' کد`
Condition of Surfacing			'S'
Riding Quality			'S'
Road Camber			15/
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			yes
() Contraction Joints	Contraction Joints provided or not (CC Pavement)		
	- on scripping		
I. Cross Drainage			YLS
(i) Condition of head	walls in Hume pipe culverts includi	ng its painting	-
Condition of Abutr	ent & Wing walls, Slab in RCC Cu	Iverts	
Condition of railing	s/slab/approach for Bridges	and the second s	
Road Furniture	The state of the s		T
Whether sign boar Stones/Pavement	d/informatory/cautionary Board/Kn oad markings are provided and m	n & 200m aintained	701
1, Compliance Histor	y Ak a Makasara ana D		
) Status of ATR's &	iny others		
	Satisfactory (S)		\ <u>S'</u>
Överall Rating :	Satisfactory but requires impre	ovement (SRI)	
	Unsatisfactory (U)		- 0044 - 2519
Zalaipioo	04/12/2020 04/12/2020	(Signatu	(41)
NAME:		(OIBIIALE	
	7/12/20 1/2/20 04/12/20	20 E	
Te la	1 A.		