

FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020	District : East. Champaran
Division : Chalcia	Length (Km): 2.905 Km
Name of the Road : Rajapur Balakothi Koolow Ranipatti to Madhupur Phulwaria	
Scheme/Programme : MAINTENANCE (New Maintenance policy 2018)	
Package No.:	Road ID No.:
Status of the Project : Ongoing/Completed/Under Maintenance	✓
Work is a case of : New Connectivity/Up Gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	—
b)	Condition of Surfacing	—
c)	Riding Quality	—
d)	Road Camber	—
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	—
4.	Compliance History	
a)	Status of ATR's & any others	—


Overall Rating :	Satisfactory (S)	—
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	—


Not - work has been not started yet.

NAME :

DESIGNATION :

(Signature)


 05/12/2020
 A.E.


 05/12/2020
 A.E.