

FIELD INSPECTION REPORT

Date of Inspection : 04-12-2020		District : E. Champarn
Division : Chakia		Length (Km): 3.20 km
Name of the Road : PMGSY Road To Bahlolpur Kalyanpur Path		
Scheme/Programme :		MAINTENANCE (OLD)
Package No.:		Road ID No.: 31708408019
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	'S'
b)	Condition of Surfacing	'U'
c)	Riding Quality	S
d)	Road Camber	'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NO
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	OK
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	No
4,	Compliance History	
a)	Status of ATR's & any others	


Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	'U'

Remarks :- Some Length of this Road damage due to Flood

NAME :

(Signature)

DESIGNATION :


 04-12-2020
 J.E