

FIELD INSPECTION REPORT

Date of Inspection : 05-12-20		District: East Chaurpawan	
Division : Road		Length (km): 2.55 Km	
Name of the Road: PEO road Silpura village to Dubaha Bazar			
Scheme/Programme: MAINTENANCE		Road Id No.: 3170850230003	
Package No.:			
Status of the Project: Quarrying/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4. Compliance History			
a)	Status of ATR's & any others	N.A.	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Syam Sunder Rai
DESIGNATION: A.E/Ch.


05/12/20
(Signature)
A.E