FIELD INSPECTION REPORT

Date of Inspection :		District:	East champaran		
Division: R.W.D. (W) Dhaka		Length (km): 2.037			
Name of the Road: Dhaka Belua Chat Road to Malkauniya.					
Scheme/Programme:	MAINTENANCE	3054 (M	<i>Ŋ</i>		
Package No.: MR-N/19	7-20 Dhaka/ 14	Road Id No	»: 317086020 63		
Status of the Project:	Ongoing/Completed/Under Maintenance				
Work is a case of:	New Connectivity/Up gradation/ Maintenance				

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	\S/U
c)	Riding Quality	√S/U
d)	Road Camber	V\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ~/
f)	Contraction Joints provided or not (CC Pavement)	Yes/No 📈
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	š/sri/u
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating

Satisfactory (S)	`S'
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	~

NAME: Shelikhurul Hodg.

DESIGNATION: A.E

, **ExSignature**)gineer R W. D. Works Division Dhaka