

FIELD INSPECTION REPORT

Date of Inspection :	4/12/2020	District:	West Champaran
Division :	Bettiah	Length (km):	
Name of the Road:	Bakuchiya to Laxmipur road under yogapatti block		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/A-20/Bettiah-12	Road Id No.:	3180880/012
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Particulars to be checked	Remarks	
Pavement			
a)	Road Junction condition	✓	S/U
b)	Condition of Surfacing	U	S/U
c)	Riding Quality	S	✓S/U
d)	Road Camber	S	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
Culverts/Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
Compliance History			
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Note:- For repair work are in progress.

R. D. S.
(Signature) 4/12/20

NAME: *Ram Dhar Chaudhary*

DESIGNATION: *Junior Engineer*