

FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020		District: W. Champaran
Division : Beltharh		Length (km):
Name of the Road: Manthaulig to Haridauri		
Scheme/Programme: MAINTENANCE		
Package No.: RM/WB/BBT/20/0005	Road Id No.: 31808802097	
Status of the Project:	Ongoing/Completed/Under Maintenance Completed	
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	-S/U
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes/No
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S/SRI/U
4.	Compliance History	
a)	Status of ATR's & any others	Yes/No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature
05/12/20
(Signature)

NAME: SUNIL KUMAR
DESIGNATION: JUNIOR ENGINEER