

FIELD INSPECTION REPORT

Date of Inspection : 05.12.2020	District: W. Champaran
Division : Belhiya	Length (km): 2.700.4
Name of the Road: Manjhauli Dhabarhan to Manjhauli Naya	
Scheme/Programme: MAINTENANCE	
Package No.: RM/NB/367/20/1005	Road Id No.: 31808802099
Status of the Project: Ongoing/Completed/Under Maintenance	0.190049
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4. Compliance History		
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

'U'

NOTE:- Agreement done on dtd 29-07-2020
But work not started.

(Signature)

NAME: SUNIL KUMAR

DESIGNATION: JUNIOR ENGINEER