

FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020		District: W. Champaran
Division : Belthigh		Length (km): 2.740
Name of the Road: Ghanuli to ghogunda		
Scheme/Programme: MAINTENANCE		
Package No.: RM/WB	BBT/19/1018	Road Id No.: 31808902043
Status of the Project: Ongoing/Completed/Under Maintenance		Completed
Work is a case of: New Connectivity/Up gradation/ Maintenance		Maint.
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature
5.12.20

NAME: Narendra Singh
DESIGNATION: EE RWD/W Dir
Belthigh