

FIELD INSPECTION REPORT

Date of Inspection :	4/12/2020	District:	West Champaran
Division :	Bettich	Length (km):	3.190 km
Name of the Road:	Hathia to Bisharampur		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20/Bettich-12	Road Id No.:	3/808902046
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Particulars to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	U S/U ✓	
b)	Condition of Surfacing	U S/U ✓	
c)	Riding Quality	U S/U ✓	
d)	Road Camber	U S/U ✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4. Compliance History			
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Note: - contract agreement has done but the work has not started still.
Contract agreement dt. 28.2.2020

LiDine
4/12/20
(Signature)

NAME: *Laxmi Dulari Chauhan*

DESIGNATION: *Junior Engineer*