

FIELD INSPECTION REPORT

Date of Inspection : 25/12/2020	District: W. Champaran
Division : Bettiah	Length (km):
Name of the Road: Mansa to Compu Path	
Scheme/Programme: MAINTENANCE	Road Id No.: S/80890266
Package No.: RM/WB/BET/19/2018	
Status of the Project: Ongoing/Completed/Under Maintenance	Completed
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Parameters to be checked			Remarks
Sl. No.			
1.	Pavement	S	-STU
a)	Road Junction condition	S	-STU
b)	Condition of Surfacing	S	-STU
c)	Riding Quality	S	-STU
d)	Road Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		S/SRUU
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRUU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRUU
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/lan & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)
Satisfactory but requires improvement (SR)
Unsatisfactory (U)


(Signature)

NAME: SUNIL KUMAR
DESIGNATION: JUNIOR ENGINEER