FIELD INSPECTION REPORT

Date of Inspection:	15-12-2020	District: West Champerson	
Division: Bayera -1		Length (km):	
Name of the Road: - (-	sam (gumake me	Jamishy Jahrman Ke gour to Ahiswelyk nedpur	
Scheme/Programme:	MAINTENANC		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

l. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/V	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber	S/W	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SKI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SKI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRÍ/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating:

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

N/A

N/A

Signature)

(Signature)

NAME: MD. Shaharshinghm

DESIGNATION: FE