## FIELD INSPECTION REPORT

Date of Inspection: 65-12-2020			District: Darbharge	
Division: Dalbhanga - 2			Length (km): 3.00 (C. 4	
Name of	the Road: L.	9. o. food to	Biopalpur Rashopur	180
Scheme/I	Programme:	MAINTENANCE		18
Package	No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is	a case of:	SALES SERVICES A SERVICES	/Up gradation/ Maintenance	Children Carlotte
SI. No.		Parameters .	to be checked	Remarks
1.	Pavement	visit (1) Directoristi	and Supplied to the Supplied S	
a)	Road Junction	condition		S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Ycs/No
2.	Cross Drains	nge in the second		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnit	ure		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance	History	Bellie malaya ("Beth" bellie	

Overall Rating

Satisfactory (S)		
Satisfactory but requires Improvement (SRI)	Harrier B	- 4
Unsatisfactory (U)		

Not applicable

HOSK not started.

NAME: SYED SHAEQUE AHMAD DESIGNATION: ART. Ergilium.

Status of ATR's & any others