FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020			District: Day bh anga		
Division: Darbhango - 2			Length (km): 정		
Name of	f the Road: 🥻	akaranda to	Bagheshevare Bhagad MR-3054 NMP-2	ti Altha	
	Programme:	MAINTENANCE		018	
Package No.:		Road Id No.:			
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
					Sl. No.
1.	Pavement	FROM MER		道。其時	
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free aggregates in o	Yes/No			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			s/sri/u	
3:	Road Furnitu	re			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR'	s & any others			

Overall Rating

Satisfactory (S)	105	
Satisfactory but requires Improvement (SRI)	,30	
Unsatisfactory (U)		

Not applicable

MOSK not started.

NAME: SYED SHAEQUE AHMAD DESIGNATION: Asst. Engineer.