## FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020		District: Darbhange,	
Division: Darbhau		Length (km): 1.9	
Name of the Road: 10	Edore love Res	1. Station to Fatchpur R.B.O. Pat	
Scheme/Programme:	MAINTENANC	E MR-3054 NMP-2018	
Package No.:	V	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivit	y/Up gradation/ Maintenance	

SI. No.	Parameters to be checked	Remarks
i.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
(c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	Societies.
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3:	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Not applicable

r r

Mosh not started.

(Signature)

NAME: SYED SHAEBUE AHMAD DESIGNATION: ASST. Engineer.