FIELD INSPECTION REPORT

Date	of Inspection:	02/2/200 ·	District:	Drobber.	
Division:		END NUMB DIM (Datigos).	Length(Km)	1. 683 lem	
Name of Road:					
Scheme/Progrmme:		Maintenance New Maint-policy 2012, 40- 4-3654			
Package No.			Road Id No.		
Status of the Project:		Ongoing/Completed/ Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
S No.					
1	Pavement				
a)	Road Junction condition				
b)	Condition of Surfacing			5/0 106	
c)	Riding Quality			S/U 21A	
d)	Road Camber				
e)	Whether free from defects such as visible cracks, exposed			S/U NA	
	aggregates in case of CC Pavement			Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank /slope & raincuts if any			Yes/No NA	
2	Cross Drainag	103/10 04			
a)	Condition of head walls in Hume pipe culverts including its				
- a j	painting			S/SRI/U NA	
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			S/SRI/U_NA	
<u>c</u>)	Condition of railing /slabs/ approach for Bridges			S/SRI/U NA	
3	Road Furniture				
	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained				
a)				Yes/No NA	
3	Complianace History				
a)	Status of ATR's & any others				
				NA:	
Overal	l Rating:				
	, , , , , , , , , , , , , , , , , , ,	Satisfactory (S)			
		Satisfactory but requires Im	provement (SRI)		
	,	Unsatisfactory (U)			

(Signature)

Name: KUMAR CHANDRAT.

Designation: ASTT CHICKER