FIELD INSPECTION REPORT

Date of	Inspection:		ALLIVA	
Division: Madhubaul				
Name o	of the Road:	A .	gth (km): 1.800 K-	
	Programme:	MAINTENANCE	mya widhayala	130 190
Packag	e No.:		d Id No.:	
Status of the Project: Ongoing/Completed Work is a case of: New Connectivity/		Ongoing/Completed/Unde	d/Index Maintenance	
		New Connectivity/Up gradation/ Maintenance		
Sl. No.	and Will could a more that are in	Parameters to be ch	ecked	Remarks
1.	Pavement	1		- Company
a)	Road Junction condition			S/U
b)	Condition of Surfacing			- S/U
c)	Riding Quality			-S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitu	ie .		many the same
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			-Yes/No
4.	Compliance H	istory	The second secon	The second
a)	Status of ATR'	s & any others		

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NA

NAME: Charle Marker Sho DESIGNATION: A. L.