

FIELD INSPECTION REPORT

| | |
|---|-----------------------|
| Date of Inspection : 04.12.2020 | District: Samastipur |
| Division : PATORI | Length (km): 11.30 Km |
| Name of the Road: BAHADURCHAK To NANDINI DHALA | |
| Scheme/Programme: MAINTENANCE | |
| Package No.: N/A | Road Id No.: — |
| Status of the Project: Ongoing/Completed/Under Maintenance | Completed |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | Maintenance |

| Sl. No. | Parameters to be checked | Remarks |
|---------|--|-------------|
| 1. | Pavement | |
| a) | Road Junction condition | S/S |
| b) | Condition of Surfacing | S/S |
| c) | Riding Quality | S/S |
| d) | Road Camber | S/S |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No YES |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No YES |
| g) | Compaction of flank/slope & raincuts if any | Yes/No YES |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/S |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/S |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U N/A |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No YES |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | No |

Overall Rating :

| | |
|---|------------------|
| Satisfactory (S) | SATISFACTORY (S) |
| Satisfactory but requires Improvement (SRI) | _____ |
| Unsatisfactory (U) | _____ |

NAME:

PRAMOD KUMAR RAY

DESIGNATION:

JUNIOR ENGINEER

(Signature)

4.12.20