


FIELD INSPECTION REPORT.

Date of Inspection : 04.12.2020		District: Samastipur
Division : PATARI		Length (km): 1.80 Km
Name of the Road: BAHADURCHAK TO NANDINI DHALA		
Scheme/Programme: MAINTENANCE		
Package No.:	N/A	Road Id No.: N/A
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Completed</u>	
Work is a case of:	New Connectivity/Up gradation/Maintenance <u>Maintenance</u>	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/W S
b)	Condition of Surfacing	S/W S
c)	Riding Quality	S/W S
d)	Road Camber	S/W S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <u>YES</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>YES</u>
g)	Compaction of flank/slope & raincuts if any	Yes/No <u>YES</u>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <u>YES</u>
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	Satisfactory (S)
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 (Signature) 4/12/20

NAME: PRAMOD KUMAR RAY
 DESIGNATION: JUNIOR ENGINEER