



TRINED DEPARTMENT

01/2019
JUNIOR ENGINEER

विवरण:-
BR0015001005
ARBIND SHAF
BINA DEVI
02/06/1982
ST - Sche
Caste

यका नाम जहाँ के BIIA
वासी है : X
मोबाइल नं० :
क्या आवेदक बिहार
सरकार में सेविदा
कर्मचारी है ? :
बैंक लेनदेन विवर
बैंक नाम :
शुल्क राशि
अन्य वि
वर

FIELD INSPECTION REPORT

Date of Inspection :	4/12/2020	District:	Begusarai
Division :	Teghra	Length (km):	9.200 K.M
Name of the Road:	Teghra Mobarkpur PWD Road near Tegraithana to Haraan PWD Road		
Scheme/Programme:	MAINTENANCE		
Package No.:	1990/2014-15	Road Id No.:	32010708001
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Remarks
Sl. No.	Parameters to be checked		
1.	Pavement		✓ S/U
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges		✓ S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Arbind Sharma
4/12/2020
(Signature)

NAME: Arbind Sharma

DESIGNATION: J.E