

FIELD INSPECTION REPORT

(Block - Jagdishpur)

Date of Inspection : 05/12/20 District : Bhagalpur		
Division : Bhagalpur	Length (Km) : 2.55 Km	
Name of the Road : Repair of road from Jamindak to Nime.		
Scheme / Programme : MAINTENANCE (MR OLD)		
Package No. :	Road Id No. : 2070320822	
Status of the Project : Ongoing / Completed / Under Maintenance		
Work is a case of : New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S / U U
b)	Condition of Surfacing	S / U U
c)	Riding Quality	S / U U
d)	Road Camber	S / U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes / No YES
g)	Cmpaction of flank/slope & raincuts if any	Yes / No YES
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U NA
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No YES
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall Rating : Riding quality is very poor.		
	Satisfactory (S)	—
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	U

Note :

NAME : Radho Ramdas Singh
 DESIGNATION : Assistant Engineer

05/12/20
 J.E.

05/12/20
 Signature AB