

FIELD INSPECTION REPORT

(Block - Jagdishpur)

Date of Inspection :	05/12/2020	District : Bhagalpur
Division : Bhagalpur	Length (Km) :	1.30 km
Name of the Road :	Repair of road from Dadwat to Aligay na Shalepur.	
Scheme / Programme :	MAINTENANCE (old MR)	
Package No. :	Road Id No. :	2070320822
Status of the Project :	Ongoing / Completed / Under Maintenance	
Work is a case of :	New Connectivity / Up gradation / Maintenance	
SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S / U U
b)	Condition of Surfacing	S / U U
c)	Riding Quality	S / U U
d)	Road Camber	S / U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes / No Yes
g)	Cmpaction of flank/slope & raincuts if any	Yes / No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall Rating :		
	Satisfactory (S)	—
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	U

Note : Riding quality is very poor.

NAME : Radha Raman Singh
DESIGNATION : Assistant Engineer

05/12/20
J.E.

05/12/20
Signature: A.E.