

FIELD INSPECTION REPORT

old MK

Date of Inspection: 05-12-20	District: Banka
Division: Banka-1	Length (km): 3.890
Name of the Road: Amarak Shahkund road to Sultanpur	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 20703508110
Status of the Project:	Ongoing/Completed/Under Maintenance ☒
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓s/No
f)	Contraction Joints provided or not (CC Pavement)	✓s/No
g)	Compaction of flank/slope & raincuts if any	✓/N
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI/U
c)	Condition of railings/slab/approach for Bridges	SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓s/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Satisfactory

Okumel
05.12.20
(Signature)

NAME: DHARMVEER KUMAR

J.E.