

FIELD INSPECTION REPORT

Date of Inspection : 05-12-2020		District: Banka
Division : Banka-1		Length (km): 2.16 km.
Name of the Road: Repair of Rd. from Banka Chakra PWD Rd. to Brahmanpur via Madhuschak		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 20703508112
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Satisfactory (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pratik
05/12/2020
(Signature)

NAME: Ashok Kumar Siula

DESIGNATION: Junior Engineer