B	-		
Date of Inspection: 4-12-2020		District: - hopalgan;	
Division: Right D. Concolago :- 1		Length (km): 2	
Name of the Road:	Lakhpatiya	Mar to Macild	
Scheme/Programme:	Lakhpatiya Mor to Masjid MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance 1/		

Sl. No.	Parameters to be checked	Remarks	
í.	Payement		
a)	Road Junction condition	VS/U	
b)	Condition of Surfacing	VS/U	
c)	Riding Quality	VSÂU	
d)	Road Camber	VS/U	
c)	Whether free from defects such as visible cracks, exposed aggregates, in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/NoV	
g)	Compaction of flank/slope & raincuts if any	Yes/No	No raincuts
2.	Cross Drainage	1.4612	17.2
a) .	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (N-A-)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U(N	-A)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U(N	i- A:)
3.	Road Furniture	1.0.	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Road Furniture not maintedna
4.	Compliance History		
a)	Status of ATR's & any others	NO ATR	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRT
Unsatisfactory (U)	

NAME: Dimesh prougad
DESIGNATION: J.E.

(Signature)