

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020		District: East Champaran.	
Division : R.W.D (W) Dhaka		Length (km): 7.70	
Name of the Road: Jhaugram to Kundwachainpur.			
Scheme/Programme: MAINTENANCE		3054 (NR)	
Package No.:		Road Id No.: 31708608150	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

NOTE:- Same parts of roads in 1st km, 2nd km, 4th km, 6th km & 7th km are damaged due to flood during Heavy Rain/Flood in year 2019-20 and 2020-21, But Road is Motorable.

NAME: Shekh Murul Hossain
DESIGNATION: A-E

05/12/2020
(Signature)
Executive Engineer
R. W. D. Works Division
Dhaka