

FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020		District: W. Champaran	
Division : Bagaha-1		Length (km): - 3.20 km	
Name of the Road: NH28B to Mehura High School taluk			
Scheme/Programme:		MAINTENANCE - Old (305A)	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/✓
c)	Riding Quality	S/✓
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

There is a truck point at Ch. 0 To 800 mt of stone chips, sand for loading/unloading in this road. Due to movement of heavy vehicles, low volume constructed rural roads, NH-28B To Mehura High School is disturbed continuously. Hence up-gradation of low volume road is required.

NAME: Md Shahamsh Alam

DESIGNATION: J.E

05/12/2020
(Signature)