

FIELD INSPECTION REPORT

Date of Inspection : 06-12-2020	District: W. Champaran
Division : Bagaha - I	Length (km): - 14.0 km
Name of the Road: - Chautarwa to Bheisoganj	
Scheme/Programme:	MAINTENANCE (MR 3054 old.)
Package No.: RM/WE/BAG/19/003 RM/WE/BAG/19/006	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks:- Constructed by MR(3054) New Maint. Policy 2018
 (i) chautarwa to Koluha & (ii) Koluha to Bheisoganj has been completed.

Mdm
 06/12/2020
 (Signature)

NAME: M.D. Shahenshah Khan

DESIGNATION: J.E