

# FIELD INSPECTION REPORT

|                                                                 |                          |
|-----------------------------------------------------------------|--------------------------|
| Date of Inspection : 05-12-2020                                 | District: BANKA          |
| Division : BANKA-2                                              | Length (km): 1.25        |
| Name of the Road: Babarchak Laelar chowk PMWSY to Durgapur Road |                          |
| Scheme/Programme: MAINTENANCE, m/r (old), 3054                  |                          |
| Package No.:                                                    | Road Id No.: 20703600823 |
| Status of the Project: Ongoing/Completed/Under Maintenance      |                          |
| Work is a case of: New Connectivity/Up gradation/ Maintenance   |                          |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | <b>Pavement</b>                                                                                                      |             |
| a)      | Road Junction condition                                                                                              | ✓ S/U       |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U       |
| c)      | Riding Quality                                                                                                       | ✓ S/U       |
| d)      | Road Camber                                                                                                          | ✓ S/U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No    |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No    |
| 2.      | <b>Cross Drainage</b>                                                                                                |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U   |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U N/A |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U N/A |
| 3.      | <b>Road Furniture</b>                                                                                                |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No    |
| 4.      | <b>Compliance History</b>                                                                                            |             |
| a)      | Status of ATR's & any others                                                                                         |             |

Overall Rating :

|                                             |          |
|---------------------------------------------|----------|
| Satisfactory (S)                            | <u>S</u> |
| Satisfactory but requires Improvement (SRI) |          |
| Unsatisfactory (U)                          |          |

(Signature) Aj  
05-12-2020

NAME: AJAY KUMAR

DESIGNATION: AE