

FIELD INSPECTION REPORT

Date Of Inspection <u>8/12/2020</u>		District <u>Bhuj</u>
Division <u>Piro</u>		Length (km): <u>5.90</u>
Name of the Road:	<u>Kurumuri to Tavar Road (Part II)</u>	
Scheme/Programme	MAINTENANCE	
Package No.:	Road Id No.: <u>10401800819</u>	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
SI No.	Parameters to be checked	Remarks
1	Pavement	<u>Fore close due to Road Construct from PMGSY-II scheme.</u>
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Ashok Kumar

Designation J.E.

Ashok
8/12/2020
(Signature)