FIELD INSPECTION REPORT

			District: M	uzaffarþu		
Date of Inspection: 04/12/2023				Length (km): 2.630		
Divisio	PL VVD VV C	T		<u> </u>		
	Programme:	hajuri to BU	CE			
Packag			Road Id No.:	3150740084	14	
Status o	of the Project:	Ongoing/Comp	leted/Under Maintena	nce		
Work is	s a case of:	The same of the sa	ity/Up gradation/ Mai	ntehance	Dominio	
Sl. No.	Parameters to be checked				Remarks	
1.	Pavement					
a)	Road Junction condition				S/U	
b)	Condition of Surfacing 5				S/U	
c)	Riding Quality 5				S/U	
d)	Road Camber S			S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No	
f)	Contraction Joints provided or not (CC Pavement)				Yes/No	
g)	Compaction of flank/slope & raincuts if any compacted				Yes/No	
2.	Cross Draina	ge	Service and service of	The second second		
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U		
3.	Road Furnitu	ESPACIAL SECURITY				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					
4.	Compliance H	listory	Att State of the s		110 0	
	Status of ATR				NO ATR	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Raman Krishana
DESIGNATION: AE