

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: BHOPUR	
Division : JAGDISHPUR		Length (km): 2.70km.	
Name of the Road: NH-30 to Gyanpura Road.			
Scheme/Programme: MAINTENANCE			
Package No.: MR-N/19-20 JAGDISHPUR/04		Road Id No.: 10401601012	
Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>			
Work is a case of: <u>New Connectivity/Up gradation/ Maintenance</u>			


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)		
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

}

N/A


 03/12/2020
 (Signature)

NAME: MANISH KUMAR, J.E.