FIELD INSPECTION REPORT

	and the second second	TELD INSPECTIO	IN KEI C	/IC1		
Date O	f Inspection	2.12.2020	I	District	Bhotpur	
Divisio	n piro	WOOKS DIVISION P	IRO I	Length (km)	: 1.10	
Name o	of the Road:	P.W.D Road	P.W.D Road to Jaisidih Road			
Scheme	e/Programme	MAINTENANCE				
Packag	e No .: RM BHI	PIR19 0006 R	load Id No	.: 10401	601020	
Status	of the Project:	Ongoing/Completeted	Ongoing/Completeted/Under Maintenance			
Work i	s a case of:	New Connectivity/Up	New Connectivity/Up gradation/Maintenance			
SI No.	Parameters to be checked				Remarks	
1	Pavment					
a)	Road Junction condition				VS/U	
b)	Condition of Surfacing				V\$/U	
c)	Riding Quality				VS/U	
d)	Road Camber				√ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement				Yes/No N'A	
f)	Contraction Joints provided or not (CC Pavement)				Yes/No N·A	
g)	Compaction of flank/slope & raincuts if any				· Yes/No 🗸	
2	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U N A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U N'A	
c)	Condition of railings/slab/approach for Bridges				S/SRI/U N· A	
3	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				VYes/No	
4	Compliance History					
a)	Status of ATR's & any others					
Overal	Rating :	Satisfactory (S)			"5"	
		Satisfactory but requires Improvement (SRI)				
		Unsatisfactory (U)			1	
Name	:-Monoy Shanlto	Unsatisfactory (U)			02/2/2/262	

Designation -J.E.

Scanned with CamScanner