

FIELD INSPECTION REPORT

Date of Inspection : 4.12.2020		District: Gopalganj
Division : Gopalganj-1		Length (km): 3.00 Km
Name of the Road: Baidutola to Phathanpatti		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U (S)
a)	Road Junction condition	S/U (S)
b)	Condition of Surfacing	S/U (S)
c)	Riding Quality	S/U (S)
d)	Road Camber	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (N/A)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	S/SRI/U (S)
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (N/A)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (N/A)
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	No ATR
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	15
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Boon
4/12/2020
AE

(Signature)
04/12/2020

NAME: Jay Kumar Tiwari

DESIGNATION: Executive Engineer