FIELD INSPECTION REPORT

ate of I Division	nspection: 4.12.2020 District: Gopagary : Gobalgong-1 Length (km): 4.00	Po. Ah
	: Go Balgang-1 Length (km): 4.00 the Road: NH-85 Lakshwar to Maryampe	1201 6
	Programme: MAINTENANCE	
ackage	No.: Road Id No.:	
	Sthe Project: Ongoing/Completed/Under Maintenance	
	a case of: New Connectivity/Up gradation/ Maintenance	Remarks
Sl. No.	Parameters to be checked	
1.	Pavement	S/U (S
a)	Road Junction condition	~\$/U (\$
b)	Condition of Surfacing	\S/U (5)
c)	Riding Quality	S/U (S)
d)	Road Camber	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- 12
	Contraction Joints provided or not (CC Pavement)	Yes/No N
f)	Compaction of flank/slope & raincuts if any	Yes/No
g)		
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) 1	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	NO ATR
a)	Status of ATR's & any others	V
		(5)
Overall	Rating Satisfactory (S)	

	15)
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Goy Kurnorr Tworrs
DESIGNATION: Executive Engineers

(Signature)