

FIELD INSPECTION REPORT

Date Of Inspection		2.12.2020	District	Bhopur
Division - PRO, BLOCK- PIR			Length (km):	2.90
Name of the Road:		Construction of Road from Sahjani at Aya-Sesam main road to Baisadli		
Scheme/Programme		MAINTENANCE		
Package No.: RM/BH/PIR/19/0002		Road Id No.: 10401801008		
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is a case of :		New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked		Remarks	
1	Pavement			
a)	Road Junction condition		✓ S/U	
b)	Condition of Surfacing		✓ S/U	
c)	Riding Quality		✓ S/U	
d)	Road Camber		✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No N/A	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any		Yes/No ✓	
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U N/A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N/A	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N/A	
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No	
4	Compliance History			
a)	Status of ATR's & any others			

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Mang Shankar Prakash

Designation - J.E.

02/12/2020
(Signature)