	F	ELD INSPE	CTION REP	ORT	
Date Of Inspection 3 12 20 20 District By				hoppur	
Divisio	on Piòo			Length (km):	0.750
Name o	of the Road:	kyrmo	orly Road r	03 - Dha	ngana
Scheme	e/Programme	MAINTENAN			0
Packag	ge No .: RM/BH/PIR/	9/0012	Road Id N	No.: 1040 180 2	004
Status of the Project : Ongoing/Completeted/Under Maintenance		Maintenance			
Work is a case of:		New Connectivity/Up gradation/Maintenance			
SI No.	Parameters to be checked			Remarks	
1	Pavment				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA	
g)	Compaction of flank/slope & raincuts if any			Yes/No No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U ↔ A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U NA	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U NA	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History				
a)	Status of ATR's & an	y others			

Overall	Rating	
O 1 C1 411	Treetann	

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

Name: Athor ruman

Designation

JE.

Taranz