

FIELD INSPECTION REPORT

Date Of Inspection <u>3/12/2020</u>		District <u>Bhojpur</u>
Division <u>Pirso</u>		Length (km): <u>1.50</u>
Name of the Road: <u>REO Road (TQ) - Darichik</u>		
Scheme/Programme		MAINTENANCE
Package No.: <u>RM/BH/PIR/19/0012</u>		Road Id No.: <u>10401802028</u>
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up gradation/Maintenance
SI No.	Parameters to be checked	Remarks
1	Pavment	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No <u>NA</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>NA</u>
g)	Compaction of flank/slope & raincuts if any	✓Yes/No <u>NO</u>
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <u>NA</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <u>NA</u>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>NA</u>
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	" S "
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Ashok Kumar

Designation

(Signature)

Ashok
3/12/2020
TE
Taxa 22