

FIELD INSPECTION REPORT

Date Of Inspection	2.12.2020	District	Bhojpur
Division - PIRo,	Block - PIRo	Length (km):	1.15
Name of the Road:	TOI PWD Road - DHANPURA (Bachani)		
Scheme/Programme	MAINTENANCE		
Package No.:	RM/BH/PIR/19/0006	Road Id No.:	10401802036
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓		
Sl No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N/A	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Manoj Shankar Prakash

Designation - J.E.

02/12/2020
(Signature)