D		FIELD INSPEC	TION REPOR	ET.	
	e Of Inspection		strict	Bhojbur	
Divisi	on - PIRO, BIO	OCK- PIRO	Le	ngth (km):	8h0Jb41 6.16
	of the Road:	TOL PWD	ROAD - PA	the state of the s	
	ne/Programme	MAINTENANC			
Packa	ge No.: RMIBHII	18)1910004	Road Id No.:	104018	0201.6
Status	of the Project:		teted/Under Mair	itenance	2246
Work is a case of:		New Connectivit	New Connectivity/Up gradation/Maintenance		*
SI No.		Parameters to be ch	Parameters to be checked		
1	Parameters to be checked Remarks Pavment Work Statt				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History	Y			1 - 2 (2) 20 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -
a)	Status of ATR's & ar	ny others		1 10	The same of

Overall Rating	Satisfactory (S)	10.01.00
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	0.1

Name: - Maney Shonler Fralsash.

Designation $-\mathcal{J}\cdot\mathcal{E}\cdot$