		FIELD INSPECTI			
Date O	e Of Inspection 03-12.20 % District			hospur	
Divisio	TINO. MIDCAS DIKO			0.99	
Name o	of the Road:	Construction of R	acd from PIRO, SIKA	rhatta ovcid 2 HCIt-Bhatbu	
Scheme/Programme MAINTENANCE			4 77	7	
Packag	e No .: RMIBHIA	21001611110	Road Id No.: 104018	05004	
Status of the Project :			Ongoing/Completeted/Under Maintenance		
Work is a case of:		New Connectivity/U	New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked		ked	Remarks	
1	Pavment Work Nort Start				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates			Yes/No	
	in case of CC Pave	ment			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture			E 2	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History			)	
a)	Status of ATR's & any others				

Overall Rating	:	Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	
		Unsatisfactory (U)	

Name: - Manog Shanlfor Problemsh.

Designation - J.E.

(Signature)